

IEC 61850 Certificate Level A¹

No. 10157892-INC 19-2545Rev1

Issued to: Prosoft-Systems Ltd. 194a Volgogradskaya St. 620102 Ekaterinburg Russian Federation

For the server product:

RES-3-61850 (P9C-3-61850) Fault Recorder Software version: 2.0 Hardware version: 1.0 S/N: 06180002

The server product has not been shown to be non-conforming to:

IEC 61850 Edition 2 Parts 6, 7-1, 7-2, 7-3, 7-4 and 8-1

Communication networks and systems for power utility automation

The conformance test has been performed according to IEC 61850-10 Edition 2, the UCA International Users Group Edition 2 Server Test Procedures version 1.0 with TPCL² 1.2.6 with product's protocol, model and technical issue implementation conformance statements: "Protocol Implementation Conformance Statement for the IEC 61850 interface in RES-3-61850, version 2.0", "Model Implementation Conformance Statement for the IEC 61850 interface in RES-3-61850, version 2.0" and "TISSUES Implementation Conformance Statement for the IEC 61850 Ed2 interface in RES-3-61850, version 2.0" and the extra information for testing: "Protocol Implementation eXtra Information for Testing (PIXIT) for the IEC 61850 interface in RES-3-61850, version 2.0".

The following IEC 61850 conformance blocks have been tested with a positive result (number of relevant and executed test cases / total number of test cases):

1	Basic Exchange (21/26)		GOOSE Publish (11/13)
2	Data Sets (4/7)	9b	GOOSE Subscribe (14/14)
5	Unbuffered Reporting (21/21)	13	Time Synchronization (5/7)
6	Buffered Reporting (30/30)	14	File Transfer (8/8)

This certificate includes a summary of the test results as carried out at NTC FSK UES in Russian Federation with UniGrid SA Simulator 1.4.461 with test suite 1.0.51 and UniCA 61850 Analyzer 5.34.02. This document has been issued for information purposes only, and the archived DNV GL verification report No. 10157892-INC 19-2544 will prevail.

The test has been carried out on one single specimen of the product as referred above and submitted to DNV GL by Prosoft-Systems. The manufacturer's production process has not been assessed. This certificate does not imply that DNV GL has approved any product other than the specimen tested.

Arnhem, May 17, 2019

US E. Henriquez

Business Leader Interoperability of Smart Power Systems

Issued by:



DNV KEMA is now DNV GL

erification Manager

 $^1\,{\rm Level}\,{\rm A}$ - Independent test lab with certified ISO 9001 Quality System $^2\,{\rm TPCL}$ - Test procedures change list

Copyright \bigcirc DNV GL Netherlands B.V. Arnhem, the Netherlands. All rights reserved. It is prohibited to update or change this certificate in any manner whatsoever, including but not limited to dividing it into parts.

Page 1/2

www.dnvgl.com contact@dnvgl.com



IEC 61850 Certificate Level A

Applicable Test Procedures from the UCA International Users Group Edition 2 Server Test Procedures version 1.0 with TPCL 1.2.6

Conformance Block		Mandatory	Conditional
1:	Basic Exchange	sAss1, sAss2, sAss3, sAssN2, sAssN3, sAssN4, sAssN5, sSrv1, sSrv2, sSrv3, sSrv4, sSrv5, sSrvN1abcd, sSrvN4	sAssN6, sSrv6, sSrv8, sSrv12, sSrvN1e, sSrvN1f, sSrvN3
2:	Data Sets	sDs1, sDs10a, sDsN1ae	sDs15
5:	Unbuffered Reporting	sRp1, sRp2, sRp3, sRp4, sRp5, sRp9, sRp14, sRp15, sRpN1, sRpN2, sRpN3, sRpN4, sRpN8	sRp6, sRp7, sRp8, sRp10, sRp11, sRp12, sRp13, sRpN5
6:	Buffered Reporting	sBr1, sBr2, sBr3, sBr4, sBr5, sBr9, sBr14, sBr15, sBr20, sBr21, sBr22, sBr25, sBr26, sBr27, sBr28, sBrN1, sBrN2, sBrN3, sBrN4, sBrN5, sBrN8	sBr6, sBr7, sBr8, sBr10, sBr11, sBr12, sBr13, sBr23, sBr24
9a:	GOOSE publish	sGop2a, sGop3, sGop4, sGop9, sGop10, sGop11	sGop1, sGop6, sGop7, sGopN1, sGopN2
9b:	GOOSE subscribe	sGos1, sGos2, sGos3, sGos5, sGos6a, sGos7, sGosN1, sGosN2, sGosN3, sGosN4, sGosN5, sGosN6	sGos4, sGos6b
13:	Time sync	sTm1, sTm2, sTmN1	sTm3, sTmN2
14:	File transfer	sFt1, sFt2ab, sFt4, sFt5, sFtN1ab	sFt2c, sFt3, sFtN1c

www.dnvgl.com contact@dnvgl.com